

# ANNUAL SURVEYS.

7882

No. 25 Survey held at London Date August 27 1841  
 on the Barge Kisco Master Rexburg  
 Tonnage 456 Built at London When built 1810  
 By whom built                      Owners Rexburg  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock London dock

Original Survey, No. 1540 Port of London, Jan 7/34 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

*This Ship is in a most Efficient State & in my opinion should remain as classed*

Committee Minute 7th Septe 1841

Character assigned 11A1

No. 4 Survey held at London Date August 24 1841  
 on the Barge Eagle Master Buckley  
 Tonnage 370 Built at Bristol When built 1839  
 By whom built                      Owners Wills  
 Port belonging to London Destined Voyage                       
 If Surveyed Afloat or in Dry Dock London dock

Original Survey, No. 145 Port of Bristol Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

*This Ship is in good Condition & in my opinion should remain as classed. at the present time cannot be recommended for alterations*

Committee Minute 7th Septe 1841

Character assigned 11A1