

## ANNUAL SURVEYS.

1945

No. 57 Survey held at London Date 21<sup>st</sup> Sept 1841  
 on the Ship Hopkin Master Milner  
 Tonnage 114 Built at London When built 1835  
 By whom built \_\_\_\_\_ Owners Hampson  
 Port belonging to London Destined Voyage both  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 454 Port of NewcastleClassed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

Is in good condition and may remain as  
closed

Committee Minute 21<sup>st</sup> Sept 1841

Character assigned

No. 515 Survey held at London Date 21<sup>st</sup> Sept 1841  
 on the Ship London Master Hambell  
 Tonnage 231 Built at Stockton When built 1840  
 By whom built \_\_\_\_\_ Owners Taylor & Co  
 Port belonging to London Destined Voyage Hambell  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 215, 231 Port of LondonClassed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

Is in fair condition fit for the service and  
if any repairs have been made for the present

Committee Minute 21<sup>st</sup> Sept 1841

Character assigned

Lloyd's Register  
 Foundation