

ANNUAL SURVEYS.

1960

No. ¹⁰³ Survey held at London Date 22 Sept 184 1
 on the "Alfred" Master
 Tonnage 135 Built at Alloa When built 1830
 By whom built Owners Craig
 Port belonging to London Destined Voyage Subtrader
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1030, 2536 Port of London

Classed A1

The Surveyor is required to state the present Condition of the

Ducks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

A strong built ship and in a condition fit for
the voyage of one species had cargo and may
remain as classed

Committee Minute 28th Sept 184 1

Character assigned A1 LB

No. ⁹⁵ Survey held at London Date 19 Sept 184 1
 on the "David Grant" Master Lawrence
 Tonnage 195 Built at Arbroath When built 1837
 By whom built Owners Lawrence
 Port belonging to Arbroath Destined Voyage Petersburgh
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 274 Port of Dundee Feb 45

Classed A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

A good efficient condition and may remain
as classed

Committee Minute 28th Sept 184 1

Character assigned A1 LB