

# ANNUAL SURVEYS.

8038

No. 253 Survey held at London Date 13 Oct 1841  
 on the St. Andrew Master Henry  
 Tonnage 195 Built at Wex When built 1835  
 By whom built Town Owners Henderson  
 Port belonging to London Destined Voyage Lisbon  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 178 Port of Leith, Lon 5399, 6811. Classed 12.4.

Surveyor is required to state the present Condition of the

Planks	Breasthooks	Captain
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Rigging	Topsides	Sails
Deck Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Stowage Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions, Is in good and efficient condition and may remain as is.

Committee Minute 15th October 1841

Character assigned 12.4.1 SL

No. 178 Survey held at London Date 13 Oct 1841  
 on the St. Andrew Master Henry  
 Tonnage 148 Built at London When built 1824  
 By whom built Town Owners Henderson  
 Port belonging to London Destined Voyage Lisbon  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 70 Port of Penzance, Lon 345, 4463, 5218. Classed 12.4.1

Surveyor is required to state the present Condition of the

Planks	Breasthooks	Captain
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Rigging	Topsides	Sails
Deck Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Stowage Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions, Is in good efficient condition fit for conveyance of any goods or cargo to or from the port of the vessel and may be continued as is.

Committee Minute 15th October 1841

Character assigned 12.4.1 SL

© 2019 Lloyd's Register Foundation