

ANNUAL SURVEYS.

8182

No. 552 Survey held at London Date 26 Nov 1841
 on the Ship Lyford Master Styner
 Tonnage 313 Built at Shildon When built 1840
 By whom built 262 Owners Goodwin
 Port belonging to London Destined Voyage Canada
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1459 Port of Newcastle, Lon. 7059

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Is in good and apparent condition
and may remain as is

Committee Minute 30th November 1841

Character assigned 10 A 1

No. Survey held at London Date 26 Nov 1841
 on the Ship Thomas Cottle Master Wade
 Tonnage Built at When built
 By whom built Owners James
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. Port of

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

See Mr. Bage's Report for previous survey. The
port of upper deck partly shifted since last report

Committee Minute 1841

Character assigned



Lloyd's Register
 Foundation