

ANNUAL SURVEYS.

8199

No. 422 Survey held at London Date 29 Nov 1841
 on the By the Clifton Master Varrell
 Tonnage 265 Built at Sunderland When built 1829
 By whom built Owners Hartnup & Co
 Port belonging to Stock Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1298 Port of Sunderland Classed 941

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears	Wales	Cables <u>1 sufficient</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Is in good and efficient condition
and may remain as classed Portenoy

Committee Minute 3rd December 1841

Character assigned SA

No. 505 Survey held at London Date 29 Nov 1841
 on the Royal Tar Master Bell
 Tonnage 915 Built at Sunderland When built 1836
 By whom built Owners Asb
 Port belonging to Exeter Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 488 Port of Sunderland Son. 6102 Classed 1041

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>1 sufficient</u>
Plank Shears	Wales	Cables <u>1 Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>ex 1841</u>

General Observations and Opinion,
 as required by the Instructions,

Is in good and efficient condition
and may remain as classed

Committee Minute 3rd December 1841

Character assigned SA



Lloyd's Register
 Foundation