

ANNUAL SURVEYS.

8241

No. 1660 Survey held at London Date Nov 184 1
 on the By British Queen Master Mickleson
 Tonnage 144 Built at Mercurine When built 1836
 By whom built _____ Owners Mickleson
 Port belonging to Mercurine Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock West India Dock

Leath 469, *
 Original Survey, No. 5632, 7199 Port of London

Classed GA1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, in every respect in an efficient state to retain her
 as required by the Instructions, present Class

[Signature]

Committee Minute 21st December 1841

Character assigned GA1

No. 43 Survey held at London Date Dec 184 1
 on the Ship Conqueror Master Duggan
 Tonnage 799 Built at Sunderland When built _____
 By whom built _____ Owners Green & Co
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock East India Dock

Original Survey, No. _____ Port of Sunderland

Classed GA1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, At the present time caulked & sheathed with yellow metal
 as required by the Instructions, and appears fully eligible to retain her present Class

[Signature]

Committee Minute _____ 184

Character assigned _____



© 2019

Lloyd's Register
 Foundation