

REPORT of SURVEY for REPAIRS.

& Change of Owners

No. Survey held at Sidon Date Dec 8. 1841 1841

on the Bk William Hyde Master

Tonnage 440 Built at Newcastle When built 1841

By whom built Owners Hyde & Son & Co

Port belonging to Sidon Destined Voyage Bombay & China

If Surveyed Afloat or in Dry Dock Ported Dry Dock

27 Nov 1841

Original Survey, No. 1666 Dated Sunderland Classed A 1

Port of Sunderland Newcastle

REPAIRS At the present time three pairs of iron rods from the Hold beam, clamps to take two bolts in the floor, caulked & sheathed with yellow metal over paper

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sufficient</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Yellow Metal Dec 1841</u>	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state to retain her present class

The Amount of Fee.....£ 2: - : - is received by me,

Committee's Minute 24th December 1841

Character assigned A 1



© 2019

Lloyd's Register Foundation

LONG12-0069