

ANNUAL SURVEYS.

8386

No. 89 Survey held at London Date Feb 2nd 1842
 on the Ship Pandora Master Barley
 Tonnage 576 Built at Shild When built 1840
 By whom built Owners at Barley
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Onion Dr

Newcastle 1493
 Original Survey, No. 1327 Port of London

Feb 1842 Classed PA1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u> </u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Topsides <u> </u>	Masts, Yards, &c. <u> </u>
Spirkettling <u> </u>	Wales <u> </u>	Sails <u>good</u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treenails <u> </u>	Anchors No. of <u>sufficient</u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u> </u>
Breasthooks <u> </u>	Rudder <u> </u>	Copper <u>over felt Feb 1842</u>
	Windlass <u> </u>	

General Observations and Opinion, At the present time bottom stripped caulked & coppered
 as required by the Instructions, over Abbot's felt - & is in a very efficient state
to retain her present Class -

Committee Minute 14th February 1842

Character assigned PA1 revised up

No. 146 Survey held at London Date Feb 2nd 1842
 on the Br West Indian Master Hodnet
 Tonnage 320 Built at Bristol When built 1829
 By whom built Owners Bridgman & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Onion slip

Original Survey, No 100, 1872 Port of London
3549, 5586,

Continued Classed 3A1 from 1839

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>Sound</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>stand themselves</u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Topsides <u>good</u>	Masts, Yards, &c. <u> </u>
Spirkettling <u>good</u>	Wales <u> </u>	Sails <u>Well found</u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treenails <u> </u>	Anchors No. of <u> </u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>good</u>
Breasthooks <u> </u>	Rudder <u> </u>	Copper <u>put on</u>
	Windlass <u> </u>	

General Observations and Opinion, Presents a very firm appearance and I am of opinion
 as required by the Instructions, may be continued on her present Class

Committee Minute 14th February 1842

Character assigned Class 3A1



© 2019

Lloyd's Register
 Foundation