

REPORT of SURVEY for REPAIRS.

Change of Owners formerly the Napier

No. _____ Survey held at London Date Feb 2nd 1842
 on the Bk John Hullitt Master _____
 Tonnage 204 Built at Sunderland When built 1841
 By whom built _____ Owners H & J Blythe
 Port belonging to London Destined Voyage Main Fair
 If Surveyed Afloat or in Dry Dock Dorset Dock

Original Survey, No. 1018 Dated March 1841 Classed G A 1

Port of Sunderland

REPAIRS Caulked & Coppered over Abbot's Felt

It is
 Feb 4th 1842. Caulked keel up to WH - Coppered to 12.9 - lower edge of
 wale

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sufficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>over Felt</u>	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state and in all respects suitable
to retain her present Class

George Bayley
 George Bayley

The Amount of Fee.....£ 1 : : : is received by me, AA

Committee's Minute 8th February 1842

Character assigned G A 1

AA

used App



© 2019

Lloyd's Register
 Foundation

LONG12-0215