

ANNUAL SURVEYS.

8400

No. 413 Survey held at London Date 11th Feb^y 1842
 on the "Rosalind" Master Galt
 Tonnage 315 Built at Sunderland When built 1835
 By whom built - Owners Harding
 Port belonging to Liverpool Destined Voyage - Aden
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 266 Port of Sunderland Classed 7A1
Liverpool 1067, 2679 & Bristol 464

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Transoms <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Topsides <u>do</u>	Sails <u>with four 2 Sails</u>
Plank Shears <u>do</u>	Wales <u>do</u>	Cables <u>2 C H & 2 Wps</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B 1 & 1 K</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>do</u>	Copper ed <u>1842</u>

General Observations and Opinion,

as required by the Instructions,

Stripped caulked from the keel up and recoppered
Several batts & treenails driven out and proved good and
the ship appears throughout in good efficient condition and may
remain as classed

Committee Minute 10 Feb^y 1842

Character assigned 7A1

No. 57 Survey held at London Date 8 Feb^y 1842
 on the Dart Master Birth
 Tonnage 179 Built at London When built 1833
 By whom built Hulson Owners Pied Ho
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 713 2906 Port of London Classed 12A1
5543, 5509, 7954,

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Transoms <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Topsides <u>do</u>	Sails <u>2 Sails Good</u>
Plank Shears <u>do</u>	Wales <u>do</u>	Cables <u>2 C H & 2 Wps</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>2 B 1 & 1 K</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

Is in good and efficient condition and
may be continued as classed

Committee Minute 11th February 1842

Character assigned 12A1



© 2019

Lloyd's Register
Foundation

LONG12-0218