

REPORT of SURVEY for REPAIRS.

8481

No. 480 Survey held at London Date Feb: 18th 23 1842
 on the Brig Sisters Master Ramsay
 Tonnage 260 Built at Hull When built 1810
 By whom built _____ Owners Frazee & Co
 Port belonging to London Destined Voyage St Vincent
 X Surveyed ~~At~~ in Dry Dock Commercial dry dock

Original Survey, No. 515, 1046, Dated 3037, 3465, 4038, 4783, 5555, 6271, Classed R. S
 Port London

REPAIRS

At the present time
 Shipped, Caulked & Repaired the Bottom
 fitted a new Rudder sternum round the Beam
 Overhauled Masts. Rigging &
 New Main Rigging, four main topmast stays & Backstays
 Two & fore topsail yards, & main topmast

Present Condition of the

Decks <u>in good Condition</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>sound where seen</u>	Capstan _____
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Pumps <u>Good overboard</u>
Spirketting <u>Good State</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good State</u>	Counter <u>Good</u>	Sails <u>well found</u>
Waterways <u>Good State</u>	Plank & Treennails <u>Good</u> (Outside to the Water's Edge)	Cables <u>well found</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Anchors No. of <u>3</u>
Breasthooks <u>Good</u>	Copper <u>New 1046</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, This vessel is in a good sound whole some condition fit to carry dry Cargo, and in my opinion well entitled to her present character R. S

The Amount of Fee.....£ : : is received by me,

Committee's Minute 14th March 1842

Character assigned Fit & sound

[Signature]

[Signature]



© 2019

Lloyd's Register
Foundation

LON 612-0304