

## ANNUAL SURVEYS.

8554

No. 259 Survey held at London Date March 18th 1842  
 on the On Appline Master \_\_\_\_\_  
 Tonnage 440 Built at Sunderland When built 1837  
 By whom built \_\_\_\_\_ Owners Brass & Co  
 Port belonging to Bristol 27 Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Sunderland Dry Dock

Sunderland 600, Lon. 3821, 3811, 4048, 6306, 8313, 8490,  
 Original Survey, No. \_\_\_\_\_ Port of London April 1842 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good & efficient*

General Observations and Opinion, Stripper copper and caulked keel up  
 as required by the Instructions,  
By Mr. not copper and recoppered as before - In my opinion  
this ship is eligible to remain as classed 11A1

Committee Minute 29th March 1842

Character assigned 11A1

George Bayley  
25 Sept 1844  
noted her as coppered in  
June 1844 at Calcutta  
Ats producing

No. 490 Survey held at London Date March 21 1842  
 on the Royal Consort Master Roman  
 Tonnage 423 Built at Sunderland When built 1840  
 By whom built \_\_\_\_\_ Owners H Mitcalf  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dawson's Dock

Sunderland 1157,  
 Original Survey, No. 6175 Port of London June 1840 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good*

General Observations and Opinion, Stripper - strong caulked. Sheathed ym on belts  
 as required by the Instructions, Strake under wale by staples standards put in, the  
shell plating, clump & culing refastened - generally  
rehailed - In my opinion she is eligible to remain classed

Committee Minute 20th March 1842

Character assigned 10A1

George Bayley  
2019  
Lloyd's Register  
Foundation