

# REPORT of SURVEY for REPAIRS.

*Change of property* 852  
 No. 129 Survey held at London Date March 16 1842  
 on the St. George Arthur Master Campbell  
 Tonnage 334 Built at Robert Town When built 1839  
 By whom built \_\_\_\_\_ Owners Joseph Jones  
 Port belonging to London Destined Voyage Bermuda  
 If Surveyed Afloat or in Dry Dock Dowson's Slip

Original Survey, No. 51230, 1827 Dated 1839 Classed A1  
 Port London

## REPAIRS

Cumulated aloft Yards generally shotted - Copper  
examined and repaired - Smooth

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

*Good* *Good* *Good* *Lev* *Cumulated* *Overhauling* *Efficient* *Lev* *Overhauling*

## General Observations and Opinion,

*This ship is in a good and efficient condition  
 her many openings is eligible to remain as is*

*George Bayley*

The Amount of Fee.....£ 2 : - : - is received by me,

Committee's Minute 29<sup>th</sup> March 1842

Character assigned A1



© 2019

Lloyd's Register  
Foundation

LONG 612-0378