

ANNUAL SURVEYS.

8631

No. 587 Survey held at London Date 15 April 1842
 on the M. W. W. Bull Master W. W. W.
 Tonnage 334 Built at Lancaster When built 1808
 By whom built — Owners W. W. W.
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 4485, 5020 Port of London
6155, 7370,

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>As when new</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>2d cuts</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>Sufficient & Good</u>
Waterways <u>do</u>	Plank and Treennails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u> <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>—</u>

General Observations and Opinion,

as required by the Instructions,

Appears throughout in good Condition
fit for the service of any & every sort of cargo & may remain as
clipped

Committee Minute 22nd April 1842

Character assigned A. 1

No. 346 Survey held at London Date 14 April 1842
 on the Eden Howard Master Eden
 Tonnage 226 Built at Maryport When built 1834
 By whom built — Owners Carrie
 Port belonging to Liverpool Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 11 Port of Maryport, Lon 1533, Sea 4000

Classed 12 A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>—</u>	Sails <u>Sufficient & Good</u>
Plank Shears <u>do</u>	Counter <u>—</u>	Cables <u>do</u> <u>do</u>
Waterways <u>do</u>	Plank and Treennails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u> <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>—</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>—</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

Is in the most excellent condition and
may remain as clipped

Committee Minute 22nd April 1842

Character assigned 12 A. 1



© 2019

Lloyd's Register
Foundation