

ANNUAL SURVEYS.

8732

No. 458 Survey held at London Date May 14th 1842
 on the Siren Master Quile
 Tonnage 112 Built at Bye When built 1841
 By whom built _____ Owners Seaman & Hunt
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Taverner Dock

Original Survey, No. 7220 Port of London

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, This vessel has been in shore and strained
 as required by the Instructions, the copper much wrinkled; shows only few beams

which are mostly severely strained, and generally but
left a large amount of the copper to be stripped off
20th May 1842
Committee Minute George Thompson George Thompson George Thompson

Character assigned George Thompson George Thompson George Thompson
George Thompson George Thompson George Thompson

No. 13 Survey held at London Date May 14th 1842
 on the Duke Park Master Smith
 Tonnage 102 Built at London When built 1828
 By whom built _____ Owners Davidson & Co.
 Port belonging to London Destined Voyage Samarcia
 If Surveyed Afloat or in Dry Dock Taverner Dock

Original Survey, No. 753 Port of London
3011, 4846, 5626, 6855,

Classed 12 A 1
Continued 1850 49 years

The Surveyor is required to state the present Condition of the

Decks <u>in good condition</u>	Transoms <u>not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>apparently good</u>
Lower Deck Beams & Fastenings <u>good</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>not strained or broken</u>
Spirkettling <u>good</u>	Wales <u>good</u>	Sails _____
Plank Shears <u>good</u>	Counter <u>good</u>	Cables <u>good & sufficient</u>
Waterways <u>good</u>	Plank and Treennails <u>good</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings <u>good</u>	Rudder <u>good</u>	Standing & Running Rigging <u>standing</u>
Breasthooks <u>good</u>	Windlass <u>good</u>	Copper <u>in good state</u>

General Observations and Opinion, The ship is in a very fair and sound state
 as required by the Instructions, and in my opinion should remain

as a class
20th May 1842
Committee Minute George Thompson George Thompson George Thompson

Character assigned George Thompson George Thompson George Thompson
George Thompson George Thompson George Thompson