

# ANNUAL SURVEYS.

8749

No. 10 Survey held at London Date May 14 1842  
 on the Ship Madagascar Master Keller  
 Tonnage 535 Built at Blackwall When built 1837  
 By whom built Green & Green Owners R Green  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 1013, Port of London May 1841 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Top-sides <u>Good</u>	Masts, Yards, &c. <u>New Main Mast Main Mast Fitted</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Barbhauling</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Efficient</u>
Waterways <u>Good</u>	Plank and Treennails (Outside to the Water's Edge.) <u>Good</u>	Anchors No. of <u>3. 1. 1</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Barbhauling</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Copper <u>Off the good slightly cracked</u>

General Observations and Opinion,  
 as required by the Instructions,

Caulked from yellow pitch upon hull - and generally  
barbhauling aloft being opinion this ship is eligible to  
remain as classed 12 A 1

Committee Minute 24<sup>th</sup> May 1842

Character assigned

12 A 1  
George Bayley

No. 10 Survey held at London Date May 14 1842  
 on the Ship Chalabar Master R. Black  
 Tonnage 637 Built at Blackwall When built 1834  
 By whom built Green & Green Owners R Green  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 1014, Port of London May 1841 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>See</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>See</u>	Timbers of the Frame <u>See</u>	Pumps <u>See</u>
Lower Deck Beams & Fastenings <u>See</u>	Top-sides <u>See</u>	Masts, Yards, &c. <u>See</u>
Spirkettling <u>See</u>	Wales <u>See</u>	Sails <u>Barbhauling</u>
Plank Shears <u>See</u>	Counter <u>See</u>	Cables <u>Efficient</u>
Waterways <u>See</u>	Plank and Treennails (Outside to the Water's Edge.) <u>See</u>	Anchors No. of <u>3. 1. 1</u>
Hatchway Comings <u>See</u>	Rudder <u>See</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>See</u>	Windlass <u>See</u>	Copper <u>Off the good</u>

General Observations and Opinion,  
 as required by the Instructions,

Caulking from yellow pitch to waterway seams the  
middle line work and the Lower Deck from the side to  
the fore of the standards - being opinion this ship is  
eligible to remain as classed 12 A 1

Committee Minute 24<sup>th</sup> May 1842

Character assigned

12 A 1  
George Bayley