

# ANNUAL SURVEYS.

8770

No. 136 Survey held at London Date May 12<sup>th</sup> 1842  
 on the Schooner Sultana Master Summers  
 Tonnage 149 Built at Prince Edward Island When built 1839  
 By whom built \_\_\_\_\_ Owners Murray  
 Port belonging to Switzerland Destined Voyage E. Havannah  
 If Surveyed Afloat or in Dry Dock Swiss ways

Original Survey, No. 3222 3681 Port of Liverpool  
4313

Classed SA 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u> Condition	Transoms	Capstan <u>good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>not seen</u>	Pumps <u>apparently good</u>
Lower Deck Beams & Fastenings <u>fair</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>good</u>	Wales <u>"</u>	Sails
Plank Shears <u>good</u>	Counter <u>"</u>	Cables <u>well found</u>
Waterways <u>good</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>fair</u>	Windlass	Copper <u>good in good state</u>

General Observations and Opinion,

as required by the Instructions,

The ship is a well fastened ship, and appears in good condition when she can be seen. Can't keep from copper up. Plank & beams on the deck, & spars, timbers supported very good.

Committee Minute 31<sup>st</sup> May 1842

Character assigned 4<sup>th</sup> A 1

No. 136 Survey held at London Date May 12<sup>th</sup> 1842  
 on the Schooner Victoria Master Thorne  
 Tonnage 150 Built at England When built 1838  
 By whom built \_\_\_\_\_ Owners London  
 Port belonging to Switzerland Destined Voyage "  
 If Surveyed Afloat or in Dry Dock Swiss ways

Original Survey, No. 163 Port of Melford London 7202

Classed SA 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>not seen</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>good</u>	Wales <u>"</u>	Sails
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>well found</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>fair</u>	Windlass <u>good</u>	Copper <u>good</u>

General Observations and Opinion,

as required by the Instructions,

A good built vessel in an efficient state, and she can be seen in the Channel.

Committee Minute 31<sup>st</sup> May 1842

Character assigned 12<sup>th</sup> A 1