

ANNUAL SURVEYS.

8789

No. 563 Survey held at London Date May 11 1842
 on the Barque City of London Master Walter
 Tonnage 240 Built at Burham When built 1838
 By whom built W. & C. Owners W. & C.
 Port belonging to London Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Mountain Ship

Original Survey, No. 22 Port of Sheekham, Lon 1812, 1870 Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Replanned & Caulked</u>	Transoms <u>Not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>" "</u>	Pumps <u>apparently Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>" "</u>	Sails <u>" "</u>
Plank Shears <u>Good</u>	Counter <u>" "</u>	Cables <u>Not found</u>
Waterways <u>Good</u>	Plank and Treennails <u>" "</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>5</u>
Hatchway Coverings <u>" "</u>	Rudder <u>" "</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>" "</u>	Copper <u>Good</u>

General Observations and Opinion, At the present time Replanned & Caulked the deck which was
as required by the Instructions, originally found, and found not to stand. Caulked Spikes
the vessel is in a very good state and should remain
as classed

Committee Minute 3rd June 1842

Character assigned W. & C. 1 W. & C. Both of Black

No. 466 Survey held at London Date May 10 1842
 on the Schooner Azorian Master Phillips
 Tonnage 105 Built at Spanish When built 1834
 By whom built " " Owners W. & C.
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Mountain Water

Original Survey, No. " " Port of " " Classed 12 B 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good when</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>" "</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>" "</u>
Spirkettling <u>Good</u>	Wales <u>" "</u>	Sails <u>" "</u>
Plank Shears <u>" "</u>	Counter <u>" "</u>	Cables <u>Not found</u>
Waterways <u>" "</u>	Plank and Treennails <u>" "</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>" "</u>
Hatchway Coverings <u>" "</u>	Rudder <u>" "</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>" "</u>	Copper <u>Not found</u>

General Observations and Opinion, At the present time Caulked the deck & Sides
as required by the Instructions, the copper. The vessel is in a very efficient state &
should remain as classed

Committee Minute " " 184" "

Character assigned " " " " Both of Black