

ANNUAL SURVEYS.

8793

No. Survey held at London Date May 31 184 2
 on the Bg Kate Master B. Brunwell
 Tonnage 103 Built at Warrington When built 1827
 By whom built Owners M. Smith & Grey
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3123 Port of London

Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Sound</u>	Pumps <u>4</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>4</u>
Spirkettling <u>Good</u>	Wales <u>4</u>	Sails <u>Not found</u>
Plank Shears <u>4</u>	Counter <u>4</u>	Cables <u>4</u>
Waterways <u>4</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>4</u>
Hatchway Coverings <u>4</u>	(Outside to the Water's Edge)	Standing & Running Rigging <u>Good</u>
Breasthooks <u>4</u>	Rudder <u>4</u>	
	Windlass <u>4</u>	

General Observations and Opinion, I am not satisfied with the condition of the ship at the present time
 as required by the Instructions, in good condition for the safe conveyance of cargo
household cargo

Committee Minute 3rd June 184 2
 Character assigned 1st LLP

No. Survey held at London Date May 31 184 2
 on the Bk Ralph Bernal Master Budge
 Tonnage 314 Built at Warrington When built 1835
 By whom built Owners Wachsmann
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Warrington Dock

Original Survey, No. 336 Port of London

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>4</u>	Timbers of the Frame <u>Sound</u>	Pumps <u>4</u>
Lower Deck Beams & Fastenings <u>4</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>4</u>
Spirkettling <u>Good</u>	Wales <u>4</u>	Sails <u>Not found</u>
Plank Shears <u>4</u>	Counter <u>4</u>	Cables <u>4</u>
Waterways <u>4</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>4</u>
Hatchway Coverings <u>4</u>	(Outside to the Water's Edge)	Standing & Running Rigging <u>Good</u>
Breasthooks <u>4</u>	Rudder <u>4</u>	Copper <u>4</u>
	Windlass <u>4</u>	

General Observations and Opinion, Not general appearance for sale and is in an
 as required by the Instructions, efficient state to continue as before

Committee Minute 3rd June 184 2
 Character assigned 1st LLP

Lloyd's Register
Foundation