

ANNUAL SURVEYS.

8818

No. ³⁰¹ Survey held at London Date June 3rd 1842
 on the Bk Charles Brooke Master Grant
 Tonnage 296 Built at Capetown When built 1825
 By whom built _____ Owners Smith & Co
 Port belonging to London Destined Voyage off Vincennes
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 1818 Port of London 1040 Redm. Classed A 1 7th June
3423, 3712, 4508, 6000, 8135.

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>sound</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>sound & heavy</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides <u>good</u>	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails <u>good</u>
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treennails <u>good</u>	Anchors No. of <u>sufficient</u>
Hatchway Coverings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks _____	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, At the present time weather for the vessel to the
 as required by the Instructions, Waterway & masts & rigging are in good condition
in water her present cargo

Committee Minute 10th June 1842

Character assigned 7th 1 AD

No. ²² Survey held at London Date June 3rd 1842
 on the Bk Bangalore Master Barnie
 Tonnage 343 Built at Guernsey When built 1841
 By whom built _____ Owners Sush & Co
 Port belonging to Guernsey Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 1016 Port of London Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails <u>good</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of <u>sufficient</u>
Hatchway Coverings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks _____	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, It is in very efficient state & may continue in
 as required by the Instructions, her present cargo

Committee Minute 10th June 1842

Character assigned 10th 1 AD

© 2019 Lloyd's Register Foundation