

# ANNUAL SURVEYS.

8834

No. 35 Survey held at London Date June 11 1842  
 on the Ship Maidstone Master Leach  
 Tonnage 818 Built at Blackwall When built 1839  
 By whom built Speculator & Co. Green Owners Mr. Higgins  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Blackwall

Original Survey, No. 5458 Blackwall Port of London

Classed 2A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>Do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Do</u>	Topsoles <u>Do</u>	Masts, Yards, &c. <u>Do</u>
Spirkettling <u>Do</u>	Wales <u>Do</u>	Sails <u>Good</u>
Plank Shears <u>Do</u>	Counter <u>Do</u>	Cables <u>Good</u>
Waterways <u>Do</u>	Plank and Treennails <u>Good</u>	Anchors No. of <u>3 11 1</u>
Hatchway Comings <u>Do</u>	Rudder <u>Do</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Do</u>	Windlass <u>Do</u>	Copper <u>Good</u>

General Observations and Opinion, This ship has diagonal Stakes showing fore and aft  
 as required by the Instructions, Mr. M. Smith is perfectly sound - Is in good order  
She is eligible to receive as classed 2A1

Committee Minute 11th June 1842

Character assigned 2A1

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 184 \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Original Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_

Classed \_\_\_\_\_

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsoles	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails	Anchors No. of
Hatchway Comings	(Outside to the Water's Edge.)	Standing & Running Rigging
Breasthooks	Rudder	Copper
	Windlass	

General Observations and Opinion,  
 as required by the Instructions,

Committee Minute \_\_\_\_\_ 184 \_\_\_\_\_

Character assigned \_\_\_\_\_

© 2019

Lloyd's Register  
 Foundation

June 11 -

2 Papers & the products

3 Annals

2 Specimens

7



© 2019

Lloyd's Register  
Foundation