

REPORT of SURVEY for REPAIRS.

No. 126 Survey held at London Date June 7 & 14 1842
 on the Steamer Odino Master Baxter
 Tonnage 219 Built at Leith When built 1840
 By whom built _____ Owners Scots etc
 Port belonging to Dundee Destined Voyage St. Austine
 If Surveyed Afloat or in Dry Dock At the Dry Dock

Original Survey, No. 524 Dated _____ Classed 7 A1
522

Port Dundee, London 6/199

REPAIRS

At the present time, Shipside of the Copper
Shipside & Planks in water Laid down bin, Caulked
from Kiel to Gunwale, & Re-coppered in paper.
The timbers show were exposed very good.

Present Condition of the

| | | |
|---|---|--|
| Decks <u>Good</u> | Transoms <u>good</u> | Windlass <u>Good</u> |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame <u>good</u> | Copstan <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u> | Pumps <u>"</u> |
| Spirketting <u>"</u> | Wales <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Plank Sheers <u>"</u> | Counter <u>"</u> | Sails <u>"</u> |
| Waterways <u>"</u> | Plank and Treenails <u>"</u> (Outside to the Water's Edge) | Cables <u>good & sufficient</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Anchor No. of <u>"</u> |
| Breasthooks <u>fair</u> | Copper <u>new 1842</u> | Standing & Running Rigging <u>Good</u> |

General Observations and Opinion,

This vessel is in a good & efficient state
in my opinion should be classified
Rating of Rank

The Amount of Fee.....£..... is received by me,

Committee's Minute 17th June 1842

Character assigned 7 A1

Lloyd's Register
 Foundation