

REPORT of SURVEY for REPAIRS.

Charge of Owners

No. 138 Survey held at Liverpool Date April 9th 1842
 on the Ship Equation Master A. Cronin
 Tonnage 657 Built at Hull When built 1842
 By whom built _____ Owners W. H. H. H.
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock East India Dock & Dry Dock

Hull 1107, Original Survey, No. 8644, Dated Feb'y 1842 Classed 11 A 1

Port of Liverpool
 REPAIRS Sheathing with yellow metal


*Can of gunpowder that is kept fully as high as it is in bottles
 as the keelsons in the hold are not well squared
 and several of them being of soft wood some of the
 beams were damaged*

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchors No. of
Breasthooks	<u>W. H. H. H. April 1842</u>	Standing & Running Rigging

General Observations and Opinion Ship in a very efficient state & well found in stores &

The Amount of Fee... £ 3 : is received by me, of Messrs
 Committee's Minute 17th June 1842
 Character assigned 11 A 1



© 2019

Lloyd's Register
 Foundation