

ANNUAL SURVEYS.

8856

No. 120 Survey held at London Date June 14th 1842
 on the Bois Odino Master Barker
 Tonnage 214 Built at Adroath When built 1840
 By whom built Owners Ashe
 Port belonging to Dundee Destined Voyage Admission
 If Surveyed Afloat or in Dry Dock At the Lys Vays

Original Survey, No. 522 Port of Dundee, London 1799 Classed 7A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>not seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Well found</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>None 1842</u>

General Observations and Opinion, At the present time. Ship's Condition
 as required by the Instructions, is such that the vessel is in a better state of repair than when last surveyed. The vessel is in good condition and may remain as classed

Committee Minute 184

Character assigned At the Lys Vays

No. 86 Survey held at London Date June 14th 1842
 on the Chas. Maitland Brown Master R. Wells
 Tonnage 122 Built at Rye When built 1840
 By whom built Owners At the Lys Vays
 Port belonging to London Destined Voyage Scotch
 If Surveyed Afloat or in Dry Dock At the Lys Vays

Original Survey, No. 295 Port of London Classed 2A, 1
3599, 3518, 3055,

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>not seen</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Well found</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>None</u>

General Observations and Opinion, The vessel is in good condition and may remain as classed
 as required by the Instructions, At the Lys Vays

Committee Minute 21st June 1843

Character assigned At the Lys Vays