

ANNUAL SURVEYS.

8857

No. 71 Survey held at London Date June 10th 1842
 on the Barque Waterhen Master Dodd
 Tonnage 155 Built at Hull When built 1835
 By whom built _____ Owners Burwell & Co.
 Port belonging to London Destined Voyage Rubber
 If Surveyed Afloat or in Dry Dock London's Quay

Original Survey, No. 226, 231 Port of London
4071, 5122, 6180, 7272,

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>in good Condition</u>	Transoms <u>not run</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>firm & good</u>	Timbers of the Frame <u>" "</u>	Pumps <u>" "</u>
Lower Deck Beams & Fastenings <u>" "</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>" "</u>
Spirketting <u>Good state</u>	Wales <u>" "</u>	Sails <u>" "</u>
Plank Shears <u>" "</u>	Counter <u>" "</u>	Cables <u>Well found</u>
Waterways <u>" "</u>	Plank and Trencails <u>" "</u> (Outside to the Water's Edge)	Anchors No. of <u>" "</u>
Hatchway Coverings <u>" "</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>firm</u>	Windlass <u>" "</u>	Copper <u>" "</u>

General Observations and Opinion,
 as required by the Instructions,

At the present time examining and
the vessel is in a good sound
State & may remain as classed

Committee Minute 21st June 1842

Character assigned A. 1

No. 585 Survey held at London Date June 10th 1842
 on the Ship Clarendon Master Fisher
 Tonnage 150 Built at London When built 1837
 By whom built _____ Owners Davidson
 Port belonging to London Destined Voyage Samarcand
 If Surveyed Afloat or in Dry Dock Mr King's dock

Original Survey, No. 607, 656 Port of London
5012, 5766, 6629, 7940,

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>very good</u>	Transoms <u>good when run</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>firm and good</u>	Timbers of the Frame <u>" "</u>	Pumps <u>" "</u>
Lower Deck Beams & Fastenings <u>" "</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>" "</u>
Spirketting <u>Good</u>	Wales <u>" "</u>	Sails <u>" "</u>
Plank Shears <u>" "</u>	Counter <u>" "</u>	Cables <u>Well found</u>
Waterways <u>" "</u>	Plank and Trencails <u>" "</u> (Outside to the Water's Edge)	Anchors No. of <u>" "</u>
Hatchway Coverings <u>" "</u>	Rudder <u>" "</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>" "</u>	Windlass <u>" "</u>	Copper <u>" "</u>

General Observations and Opinion,
 as required by the Instructions,

At the present time both above the quarter galleries
shipped a few short planks in short -
The ship is in a very firm & good state with
and should be in my opinion as classed

Committee Minute 21st June 1842

Character assigned A. 1