

# ANNUAL SURVEYS.

8890

No. 476 Survey held at London Date July 1 1842  
on the Bayne British Isles Master Burhead  
Tonnage 531 Built at Sunderland When built 1834  
By whom built \_\_\_\_\_ Owners Lucie & Co  
Port belonging to London Destined Voyage Dennara  
If Surveyed Afloat or in Dry Dock Dennara

Original Survey, No. 755 Port of Sunderland, Lon 3944, Classed NA 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>not seen</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good &amp; new</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topides <u>good</u>	Masts, Yards, &c. <u>good</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails
Plank Sheers <u>"</u>	Counter <u>"</u>	Cables <u>good and</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Coverings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>in good condition</u>

General Observations and Opinion,  
as required by the Instructions,

This ship is in a very good state & should remain as classed.

Committee Minute 5th July 1842

Character assigned NA 1

No. 126 Survey held at London Date July 20 1842  
on the Brig Bedford Master Edwitt  
Tonnage 116 Built at Barnmouth When built 1810  
By whom built \_\_\_\_\_ Owners Capt.  
Port belonging to Barnmouth Destined Voyage Coast.  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 535 Port of London, Mov 620, Sir 3711, Classed NA 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>not seen</u>	Capstan
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>good &amp; new</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>fair</u>	Topides <u>good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>good</u>	Wales <u>"</u>	Sails
Plank Sheers <u>"</u>	Counter <u>"</u>	Cables
Waterways <u>fair &amp; somewhat new good</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Coverings <u>good</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper

General Observations and Opinion,  
as required by the Instructions,

This vessel is in a good wholesome state & may remain as classed.

Committee Minute 5th July 1842

Character assigned NA 1

Lloyd's Register  
Foundation