

ANNUAL SURVEYS.

89014

No. 421 Survey held at London Date July 9th 1842
 on the Bayne & Charles Bayne Master Bayne
 Tonnage 531 Built at Merimbou When built 1841
 By whom built Bayne Owner Bayne
 Port belonging to Glasgow Destined Voyage India & back to London
 If Surveyed At Sea or in Dry Dock Casters dock

Original Survey, No. 1080 Port of Clyde Classed 4A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>well fastened</u>	Timbers of the Frame <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Good & well</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good</u>
Waterways <u>"</u>	Plank and Treecails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion,
 as required by the Instructions,

The Ship is in very good Condition & in my opinion should remain as such.

Committee Minute 19th July 1842

Character assigned 4A 1

No. 13 Survey held at London Date July 9th 1842
 on the Ship "Geminio" Master Ang
 Tonnage 517 Built at Port Glasgow When built 1841
 By whom built Ang Owners Ang & Co.
 Port belonging to Port Glasgow Destined Voyage "
 If Surveyed At Sea or in Dry Dock Port Glasgow

Original Survey, No. 994 Port of Clyde Classed 12A 1

The Surveyor is required to state the present Condition of the

Decks <u>very good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Good & well</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good</u>
Waterways <u>"</u>	Plank and Treecails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Good</u>

General Observations and Opinion,
 as required by the Instructions,

a small portion of the Ship is in excellent condition & should remain as such.

Committee Minute 12th July 1842

Character assigned 12A 1