

ANNUAL SURVEYS.

8998

No. 422 Survey held at London Date Aug: 9th 1842
 on the Bayne Lady Catherine Master Freeman
 Tonnage 321 Built at London When built 1834
 By whom built Owners Stanley
 Port belonging to London Destined Voyage West Indies (Samoa)
 If Surveyed Afloat or in Dry Dock Ships' Landing St.

Original Survey, No. 385, 367 Port of London
4143, 4657, 8115,

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>very good</u>	Transoms <u>good where run</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u>good</u>	Top-sides <u>good</u>	Masts, Yards, &c. <u> </u>
Spirkettling <u>good</u>	Wales <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u>good &</u>
Waterways <u> </u>	Plank and Treennails <u> </u> (Outside to the Water's Edge.)	Anchors No. of <u>half ton &c</u>
Hatchway Coverings <u> </u>	Rudder <u> </u>	Standing & Running Rigging <u> </u>
Breasthooks <u> </u>	Windlass <u> </u>	Copper <u>good</u>

General Observations and Opinion,
 as required by the Instructions,

*This Ship is in a most efficient State, & in
 my opinion should remain as classed 12 A 1*

Committee Minute 16th August 1842

Character assigned 12 A 1

No. 422 Survey held at London Date August 11 1842
 on the Bayne Elizabeth Master Medwin
 Tonnage 327 Built at Southampton When built 1836
 By whom built Owners Stanley
 Port belonging to London Destined Voyage Samoa
 If Surveyed Afloat or in Dry Dock

Original Survey, No. 385, 278 Port of London
3653, 5406, 7115,

Classed A 1

The Surveyor is required to state the present Condition of the

Decks <u>very good</u>	Transoms <u>good where run</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u>good</u>	Top-sides <u>good</u>	Masts, Yards, &c. <u> </u>
Spirkettling <u>good</u>	Wales <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u>good &</u>
Waterways <u> </u>	Plank and Treennails <u> </u> (Outside to the Water's Edge.)	Anchors No. of <u>half ton &c</u>
Hatchway Coverings <u> </u>	Rudder <u> </u>	Standing & Running Rigging <u> </u>
Breasthooks <u> </u>	Windlass <u> </u>	Copper <u>good</u>

General Observations and Opinion,
 as required by the Instructions,

*This Ship is in excellent order throughout
 and in my opinion should remain as classed*

Committee Minute 16th August 1842

Character assigned 12 A 1

Lloyd's Register
 Foundation