

ANNUAL SURVEYS.

9007

No. 128 Survey held at LONDON Date 9 Aug 1842
 on the Ed Reform Master Portoff
 Tonnage 104 Built at Boston When built 1831
 By whom built - Owners Portoff
 Port belonging to Boston Destined Voyage - Kitterum
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 2755, 533 (Port of London)
 The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>1</u>	Pumps
Lower Deck Beams & Fastenings	Topsides <u>1</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>1</u>	Sails <u>As before</u>
Plank Shears <u>1</u>	Counter <u>1</u>	Cables <u>As</u> <u>As</u>
Waterways <u>1</u>	Plank and Treenails (Outside to the Water's Edge.) <u>1</u>	Anchors No. of <u>As</u> <u>As</u>
Hatchway Comings <u>1</u>	Rudder <u>1</u>	Standing & Running Rigging <u>As</u> <u>As</u>
Breasthooks <u>1</u>	Windlass <u>1</u>	Copper

General Observations and Opinion,
 as required by the Instructions, It is in the most efficient condition and was
examined as before

Committee Minute 10th August 1842

Character assigned Good 3

No. 17 Survey held at LONDON Date 9 Aug 1842
 on the Edith Master Langley
 Tonnage 127 Built at Dartmouth When built 1831
 By whom built - Owners Langley
 Port belonging to Dartmouth Destined Voyage South
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 536 Port of London, Date 78, 151, Jan 136,
 The Surveyor is required to state the present Condition of the

Decks <u>Good fair</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>As before</u>	Pumps
Lower Deck Beams & Fastenings <u>1</u>	Topsides <u>1</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>1</u>	Sails <u>As before</u>
Plank Shears <u>1</u>	Counter <u>1</u>	Cables <u>As</u> <u>As</u>
Waterways <u>1</u>	Plank and Treenails (Outside to the Water's Edge.) <u>1</u>	Anchors No. of <u>As</u> <u>As</u>
Hatchway Comings <u>1</u>	Rudder <u>1</u>	Standing & Running Rigging <u>As</u> <u>As</u>
Breasthooks <u>1</u>	Windlass <u>1</u>	Copper

General Observations and Opinion,
 as required by the Instructions, It is in good condition fit for the service and
if dry & openable & may be continued as before

Committee Minute 10th August 1842

Character assigned Good 1