

## ANNUAL SURVEYS.

9084

No. 20 Survey held at LONDON Date 23 Sept 1842  
 on the the Conservative Master Cousins  
 Tonnage 245 Built at Sunderland When built 1840  
 By whom built - Owners Freene  
 Port belonging to LONDON Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1791 Port of Sunderland, Lon 657, 8062, 8070 Classed 1st A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good &amp; Sufficient</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do &amp; Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>"</u>
Plank Sheers <u>"</u>	Counter <u>do</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>do</u> (Outside to the Water's Edge.)	Anchor No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>do</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>do</u>	Copper <u>"</u>

General Observations and Opinion,  
 as required by the Instructions,

Is in good & efficient condition, and may remain as classed Hourway

Committee Minute 30th September 1842

Character assigned 1st A1

No. 20 Survey held at LONDON Date 26 Sept 1842  
 on the the Foxhound Master Bees  
 Tonnage 117 Built at Farmouth When built 1836  
 By whom built - Owners Palmer  
 Port belonging to Farmouth Destined Voyage Farmouth & Trade  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 130 Port of Farmouth, Sea 3067, Sea 2000 Classed 1st A1  
Sea 4250, Sea 5113.

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>"</u>	Pumps <u>Good &amp; Sufficient</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>do</u>
Plank Sheers <u>"</u>	Counter <u>"</u>	Cables <u>do</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchor No. of <u>do</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Good</u>

General Observations and Opinion,  
 as required by the Instructions,

Is in an efficient condition and may remain as classed Hourway

Committee Minute 30th September 1842

Character assigned 1st A1