

ANNUAL SURVEYS.

9114

No. 100 Survey held at Sidon Date Sept. 30th 184 2
 on the Bk Rosalind Master Reynolds
 Tonnage 317 Built at Stockton When built 1824
 By whom built Owners Leanne
 Port belonging to Sidon Destined Voyage Harannah
 If Surveyed Afloat or in Dry Dock Sidon Dock

Original Survey, No. 1005, 2888, Port of Sidon 1030 Stockton Classed & A 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound & wherever</u>	Pumps
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>good</u>	Masts, Yards, &c.
Spirkettig <u>good</u>	Wales <u>"</u>	Sails <u>good</u>
Plank Sheers <u>"</u>	Counter <u>"</u>	Cables
Waterways <u>"</u>	Plank and Treennails <u>good</u> (Outside in the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>good</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass	Copper

General Observations and Opinion At the present time, cautions about the vessel on appearance as required by the Instructions, in good condition to continue as before

Committee Minute 7th October 184 2

Character assigned Good

No. 383 Survey held at Sidon Date September 30th 184 2
 on the Buy Grecian Master Richardson
 Tonnage 212 Built at Yarmouth When built 1814
 By whom built Owners Richardson
 Port belonging to Sidon Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Sidon Dock

Original Survey, No. 244, 349, Port of Sidon 1024 Classed & A 1 Stockton

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>Sound</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & wherever</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>"</u>
Spirkettig <u>good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Sheers <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>good</u> (Outside in the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>good</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass	Copper <u>"</u>

General Observations and Opinion At the present time, cautions about the vessel on appearance as required by the Instructions, in good condition to continue as before

Committee Minute 7th October 184 2

Character assigned Good