

# ANNUAL SURVEYS.

9115

No. 326 Survey held at London Date Sept 30<sup>th</sup> 1842  
 on the Schooner Wendell Master Borer  
 Tonnage 147 Built at Litchampton When built 1841  
 By whom built \_\_\_\_\_ Owners Liberal & Co  
 Port belonging to London Destined Voyage Rotterdam  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 7943 Port of London Classified 12 A 1

The Surveyor is required to state the present Condition of the

| Decks                         | Transoms  | Capstan                    |
|-------------------------------|---|----------------------------|
| Upper Deck Beams & Fastenings | Timbers of the Frame  | Pumps                      |
| Lower Deck Beams & Fastenings | Topsides  | Masts, Yards, &c.          |
| Spirkettling                  | Wales   | Sails                      |
| Plank Shears                  | Counter   | Cables                     |
| Waterways                     | Plank and Treennails<br><small>(Outside to the Water's Edge.)</small> | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
| Breasthooks                   | Windlass  | _____                      |

General Observations and Opinion, in a very high state of efficiency and appears in  
 as required by the Instructions, all respects & slight to be added her present shape

*M. W. [Signature]*

Committee Minute 7<sup>th</sup> October 1842

Character assigned 12 A 1 *[Signature]*

No. 322 Survey held at London Date September 30<sup>th</sup> 1842  
 on the Schooner Merton Master Burdoley  
 Tonnage 122 Built at Brixham When built 1841  
 By whom built \_\_\_\_\_ Owners Burdoley  
 Port belonging to Brixham Destined Voyage Verona  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 320 Port of Dartmouth Classified 12 A 1

The Surveyor is required to state the present Condition of the

| Decks                         | Transoms  | Capstan                    |
|-------------------------------|---|----------------------------|
| Upper Deck Beams & Fastenings | Timbers of the Frame  | Pumps                      |
| Lower Deck Beams & Fastenings | Topsides  | Masts, Yards, &c.          |
| Spirkettling                  | Wales   | Sails                      |
| Plank Shears                  | Counter   | Cables                     |
| Waterways                     | Plank and Treennails<br><small>(Outside to the Water's Edge.)</small> | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
| Breasthooks                   | Windlass  | Copper                     |

General Observations and Opinion, in all respects in an efficient state to retain  
 as required by the Instructions, her present shape

*M. W. [Signature]*

Committee Minute 7<sup>th</sup> October 1842

Character assigned 12 A 1 *[Signature]*

© 2019 Lloyd's Register Foundation