

REPORT of SURVEY for REPAIRS.

9145

No. 531 Survey held at London Date Aug 28th 1842
 on the H^o Boston Castle Master Robert
 Tonnage 450 Built at Bristol When built 1819
 By whom built — Owners Charles H^o
 Port belonging to London Destined Voyage Spain & Home
 If Surveyed Afloat or in Dry Dock At H^o Ship & Afloat

Original Survey, No. 425477 Dated — Classed F.1

Port London Ply. 537 Lon. 7284 219.8981.

REPAIRS Aug 28th 1842 The main keelson trimmed down and a new Rida keelson along it - shrouns of pitch some parts new sheer strokes - and some planks sheued in the Deck, an additional Iron Breast Hook near fore mast length of lower wale at the bow each side Caution from the lower part of the wales up.

Present Condition of the	Transoms	Windlass
Decks <u>Good</u>	<u>Good</u>	<u>Good</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>No rotting</u>	Capstan
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Pumps
Spirkettling <u>Good</u>	Wales	Masts, Yards, &c. <u>Efficient Good</u>
Plank Sheers	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Iron Nailing up</u>	Standing & Running Rigging

General Observations and Opinion,

It now in an efficient condition fit for the service of any species of water transport and may remain as shipped

The Amount of Fee £ 2 is received by me, —
 Committee's Minute 11th September 1842
 Character assigned Record repairs

Lloyd's Register
Foundation