

ANNUAL SURVEYS.

9361

No. 426 Survey held at London Date Jan 2nd 1843
 on the Ship Trofic Master Phillips
 Tonnage 369 Built at London When built 1819
 By whom built _____ Owners Daniel Ho
 Port belonging to London Destined Voyage Barbadoes
 If Surveyed Afloat or in Dry Dock Bullhead Dock

Original Survey, No. 664, 4915 Port of London July 1841 Classed *F.1
6040 * 6721, 7730,

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>4</u>	Timbers of the Frame <u>4</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>4</u>	Topsides <u>4</u>	Masts, Yards, &c. <u>4</u>
Spirkettling <u>4</u>	Wales <u>4</u>	Sails <u>Overhauling</u>
Plank Shears <u>4</u>	Counter <u>4</u>	Cables <u>Efficient</u>
Waterways <u>4</u>	Plank and Treenails (Outside to the Water's Edge.) <u>4</u>	Anchors No. of <u>4</u>
Hatchway Comings <u>4</u>	Rudder <u>4</u>	Standing & Running Rigging <u>4</u>
Breasthooks <u>4</u>	Windlass <u>4</u>	Copper <u>Smooth Good ref 1843</u>

General Observations and Opinion, After piece of False keel put to rights and secured - she is in
 as required by the Instructions, my opinion fit for the conveyance of dry and perishable Cargo to
from all parts of the world and eligible to be classed *F.1

Committee Minute 13th January 1843 George Bayley
 Character assigned *F.1 asterisk

No. 272 Survey held at London Date Jan 2nd 1843
 on the Richmond Will Master _____
 Tonnage 234 Built at N Brunswick When built 1828
 By whom built _____ Owners Dowell - Wapping
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Hackwoods Dry Dock

Original Survey, No. 192, 1912 Port of London May 1840 Classed SS 1838
2650, 2948, 3332, 3774, 4158, 5524, 6090, 7564 4 years - F.1

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion, Stripped the copper off - The wood sheathing having been
 as required by the Instructions, put on in 1836 and the vessel opened and specially surveyed
in 1838 as per Rule section 63 page 18 - Called the attention of the
owner to the Rules sections 63 & 67 - with which he declined
compliance - Her general appearance
is favorable

Committee Minute 13th January 1843 George Bayley
 Character assigned Exchange Character
"Not op"

London 4-0011