

REPORT of SURVEY for REPAIRS.

Change of property 9380

No. 101 Survey held at London Date January 17th 1843
 on the M^r Senator Master Brown William
 Tonnage 346 on 351 Register Built at Northam When built 1842 - First Registered 1843 Jan 4
 By whom built J Vaux Owners John & Co
 Port belonging to London Destined Voyage Direct to West Indies Trinidad
 If Surveyed Afloat or in Dry Dock New frame

Original Survey, No. 101 Dated 12 Classed 12

Port Southampton

REPAIRS Topsides and wales caulked a few months since at Southampton - at the present time being caulked from keelson to wale and sheathed with yellow metal upon dry paper to the wale -

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, This ship was under the special consideration of the Committee in October last and called to
12 A 1

George Bayley

The Amount of Fee.....£ 2:--: is received by me,

Committee's Minute 20th January 1843

Character assigned 12 A 1

LON 614-0031

© 2019

Lloyd's Register Foundation