

# ANNUAL SURVEYS.

No. 9399 Survey held at London Date Jan 24 1843  
on the Steam Vessel Wilkesforce Master H. Stannard  
Tonnage \_\_\_\_\_ Built at London When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners Genl Stannard & Co  
Port belonging to London Destined Voyage Antwerp  
If Surveyed Afloat or in Dry Dock At Nathaniel

Original Survey, No. \_\_\_\_\_ Port of London Classed \_\_\_\_\_

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, *with the exception of a trifling damage to the Deck, as required by the Instructions, in the place there is in a good and efficient condition to remain as classed*

Committee Minute \_\_\_\_\_ 184

Character assigned \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 184  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Original Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,  
as required by the Instructions,

Committee Minute \_\_\_\_\_ 184

Character assigned \_\_\_\_\_

