

ANNUAL SURVEYS.

9175

No. 86 Survey held at M M M Date 17 Oct 1842
 on the M M M Master Boyd
 Tonnage 308 Built at Summerville When built 1837
 By whom built Thompson Owners Thompson
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1233, 1447, 1457, 5375, 7017, 7890, Port of London Classed M M

The Surveyor is required to state the present Condition of the

| | | |
|---|--|-------------------------------------|
| Decks <u>good</u> | Transoms <u>good</u> | Capstan |
| Upper Deck Beams & Fastenings <u>firm</u> | Timbers of the Frame <u>"</u> | Pumps <u>Sufficient</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Spirkettling <u>good</u> | Wales <u>"</u> | Sails <u>good</u> |
| Plank Shears <u>"</u> | Counter <u>"</u> | Cables <u>"</u> |
| Waterways <u>"</u> | Plank and Treenails <u>"</u> (Outside to the Water's Edge.) | Anchors No. of <u>"</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Standing & Running Rigging <u>"</u> |
| Breasthooks <u>"</u> | Windlass <u>"</u> | Copper <u>good & clean</u> |

General Observations and Opinion,

as required by the Instructions,

Is in a good and efficient condition
may remain as classed
Country

Committee Minute 21st October 1842

Character assigned 10 A

No. 82 Survey held at London Date 17 Oct 1842
 on the M M M Master Simpson
 Tonnage 311 Built at Yarmouth When built 1825
 By whom built Beckford Owners Beckford
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock

Original Survey, No. 997, 2516, 2903, 4134, 4650, 6772, 7715, Port of London Classed 10 A

The Surveyor is required to state the present Condition of the

| | | |
|---|--|--|
| Decks <u>good</u> | Transoms <u>good</u> | Capstan |
| Upper Deck Beams & Fastenings <u>firm</u> | Timbers of the Frame <u>"</u> | Pumps |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>"</u> | Masts, Yards, &c. <u>good & sufficient</u> |
| Spirkettling <u>good</u> | Wales <u>"</u> | Sails <u>"</u> |
| Plank Shears <u>"</u> | Counter <u>"</u> | Cables <u>"</u> |
| Waterways <u>"</u> | Plank and Treenails <u>"</u> (Outside to the Water's Edge.) | Anchors No. of <u>"</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Standing & Running Rigging <u>"</u> |
| Breasthooks <u>"</u> | Windlass <u>"</u> | Copper |

General Observations and Opinion,

as required by the Instructions,

Is in good sufficient condition and may
remain as classed
Country

Committee Minute 21st October 1842

Character assigned 7 A



© 2019

Lloyd's Register
Foundation

LON 614-0252