

9193
H

REPORT of SURVEY for REPAIRS.

No. 116 Survey held at London Date July 13th 25 1842
in the Barge "Apollo" Master Milne
Tonnage 289 Built at Garnant When built 1827
By whom built _____ Owners Stewart & Co
Port belonging to London Destined Voyage West Indies
Surveyed Afloat or in Dry Dock Bowditch Dock

Original Survey, No. 313.1034 Dated 3506, 4844, 5769, 7841, Classed 12 * A. 1
Port London

REPAIRS At the present time -
Shipped the sheer strakes, sides, & part of the
blackstrakes except the foremast & after shifts;
all new chain plates & bolts; new fastenings &
knives & caulking from the copper up -

Present Condition of the

Decks <u>Good</u>	Transoms _____	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good when run</u>	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Masts, Yards, &c. _____
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>good &</u>
Waterways <u>"</u>	Plank & Treenails (Outside to the Water's Edge) <u>"</u>	Cables <u>well furnished</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of _____
Breasthooks <u>firm</u>	Copper <u>in good condition</u> <u>Repaired</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion, This Ship is in an efficient state, fit for the safe
conveyance of dry perishable cargoes to and from all
parts of the world; and in my opinion should remain
as classed; - All the timbers that were exposed were square
and perfectly sound.

The Amount of Fee.....£ 1 : : is received by me, Wm. J. Clark

Committee's Minute 1st November 1842

Character assigned 2, 1 asterisk
H Q



© 2019
Lloyd's Register
Foundation
LON614-0273