

ANNUAL SURVEYS.

No. _____ Survey held at London Date Nov. 4th 1842
 on the Schooner Galway Lass Master Davis W. Gilbey & Moore
 Tonnage 220 Built at Sunderland When built 1839
 By whom built _____ Owners Gilbey
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Brisps Way

Original Survey, No. _____ Port of Liverpool Decr 1841 Classed 10A1

The Surveyor is required to state the present Condition of the

Planks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Planking	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

Good *Good* *Good and efficient*

General Observations and Opinion, Overhauled aloft - Copper repaired - In a
 as required by the Instructions, good and efficient state for remaining as

Classed 10A1 George Bayley 2019

Committee Minute _____ 184

Character assigned _____



Lloyd's Register
Foundation

LONDON 14-0278