

ANNUAL SURVEYS.

9271

No. 298 Survey held at London Date 13 Dec 1842
 on the M. S. Graham Master Jennings
 Tonnage 262 Built at Chipston When built 1831
 By whom built London Owners Mutiny
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1385 Port of London, Lic. 2108, Lic. 1711, 6040, Classed 10 A1
8361.

The Surveyor is required to state the present Condition of the

| | | |
|---|---|---|
| Decks <u>Good</u> | Transoms <u>Good</u> | Capstan |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame | Pumps <u>Good</u> |
| Lower Deck Beams & Fastenings <u>Good</u> | Topsides <u>Good</u> | Masts, Yards, &c. <u>Sufficient</u> |
| Spirkettling <u>Good</u> | Wales | Sails |
| Plank Shears | Counter | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of <u>3 Bower too light</u> |
| Hatchway Comings | Rudder | Standing & Running Rigging <u>Good</u> |
| Breasthooks | Windlass | Copper |

General Observations and Opinion,
 as required by the Instructions, Several keelsons were drawn out for inspection
and proved good 4 ITHK on each side now put to
hold beams. The appears in good condition in every visible
 Committee Minute 6th December 1842
 Character assigned A1
part and is fit for the conveyance
of dry & perishable cargo & may
remain as Classed when 3 B.A. is
supplied Plentyway

No. 312 Survey held at London Date 3 Dec 1842
 on the M. P. M. Monarch Master Graham
 Tonnage 312 Built at Sheddy When built -
 By whom built London Owners Graham
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat West India Dock

Original Survey, No. - Port of - Classed -

The Surveyor is required to state the present Condition of the

| | | |
|---|---|--|
| Decks <u>Good</u> | Transoms <u>Good</u> | Capstan |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame | Pumps |
| Lower Deck Beams & Fastenings <u>Good</u> | Topsides | Masts, Yards, &c. <u>Good</u> |
| Spirkettling <u>Good</u> | Wales | Sails <u>Sufficient</u> |
| Plank Shears | Counter | Cables <u>Sufficient</u> |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of <u>2 anchor block</u> |
| Hatchway Comings | Rudder | Standing & Running Rigging <u>Good</u> |
| Breasthooks | Windlass | Copper |

General Observations and Opinion,
 as required by the Instructions, The Hull is in good condition. The
chain cables are corroded and are too small holes
have been given to the owners at this date is about 6
 Committee Minute 184
 Character assigned Sail -

LONDON 4-0356