

REPORT of SURVEY for REPAIRS.

9274
JL

No. 277 Survey held at London Date Nov 18 1842
 on the Bk Gloucester Master Thomas Beard
 Tonnage 297 Built at Gloucester When built 1833
 By whom built _____ Owners Glendinning
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Kings Dock

Original Survey, No. 847, 3137, Dated 1835 Classed 12A1
1280, 5111,
 Port London

REPAIRS New Prospekt Shipped Bottom caulked from
Kill to Wall - Hung - & coppered on Hemp felt
to 13 feet

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

Survey opinion this ship is eligible to remain
as classed 12A1

George Bayley

The Amount of Fee.....£ 1 : - : is received by me, HA

Committee's Minute 9th December 1842

Character assigned 12 A 1 used App



© 2019

Lloyd's Register
Foundation

LON 674-0360