

# ANNUAL SURVEYS. *Change of Owner*

*LON 9333*

No. *4558* Survey held at *Swansea* Date *Dec. 2* 184*1*  
 on the *Bague Bengalee* Master *Boada*  
 Tonnage *305* Built at *Dumfries* When built *1837*  
 By whom built *C* Owners *Capt. L. C.*  
 Port belonging to *Whitchurch* Destined Voyage *Canton*  
 If Surveyed Afloat or in Dry Dock *afloat*

Original Survey, No. *400* Port of *Clyde* Classed *12A1*

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <i>3 Bowers 14 lb / Red</i>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

*Good* *Apparently Good* *Appear Good* *Well formed* *Good* *Good Raw is present*

General Observations and Opinion,  
 as required by the Instructions,

*Appears in good & efficient condition fit for the conveyance  
 of dry & perishable cargoes to & from all parts of the world in safety & convenience  
 as to continue as before*

Committee Minute 184

Character assigned

LON 614-0420



