

## ANNUAL SURVEYS.

9333

No. 275 Survey held at London Date Dec 20<sup>th</sup> 1842  
 on the Brig Sisters Master Barrett  
 Tonnage 243 Built at Whitby When built 1840  
 By whom built \_\_\_\_\_ Owners Whitwood  
 Port belonging to Whitby Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Miss Fletcher

Original Survey, No. 153 Port of Whitby Classed GA 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>not seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>"</u>	Wales <u>"</u>	Sails _____
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>well found</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u>	Anchors No. of _____
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper _____
	Windlass <u>"</u>	

General Observations and Opinion,  
 as required by the Instructions,

At the present time Caution the bottom  
The vessel is in good condition and may  
remain as classed

Committee Minute 3<sup>rd</sup> January 1843

Character assigned GA 1

No. 285 Survey held at London Date Dec 20<sup>th</sup> 1842  
 on the Brig Felia Master Burton  
 Tonnage 207 Built at Boston When built 1828  
 By whom built \_\_\_\_\_ Owners Whitwood  
 Port belonging to London Destined Voyage Shetland  
 If Surveyed Afloat or in Dry Dock Miss Fletcher

Original Survey, No. 774 249 Port of London Nov 1887 Classed \* E, 1  
4534, 6128

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Sum</u>	Timbers of the Frame <u>from where run</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>Sum</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails _____
Plank Shears <u>"</u>	Counter <u>"</u>	Cables _____
Waterways <u>"</u>	Plank and Treenails <u>"</u>	Anchors No. of <u>well found</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper _____
	Windlass <u>"</u>	

General Observations and Opinion,  
 as required by the Instructions,

At the present time found a fair port,  
Caution from the blue overcast. The vessel  
is in a good state, fit to carry any perishable goods  
if once from all parts of the world and may  
remain as classed E, 1 with the

Committee Minute 3<sup>rd</sup> January 1843

Character assigned GA 1



© 2019

Lloyd's Register  
 Foundation

60614-0421