

ANNUAL SURVEYS.

9596

No. 11 Survey held at London Date March 17th 20th 1843
 on the By Anne Master English
 Tonnage 234 Built at Sunderland When built 1832
 By whom built _____ Owners English
 Port belonging to Synn Destined Voyage Baltic
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 1969 Port of Sunderland Lon 7851 1841 Classed Best 5 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	<u>Copper</u>

General Observations and Opinion,
 as required by the Instructions,

*At the present time in consequence of having been
 on shore has been hung, caulked from the keel & sole
 started treenails renewed & two additional bolts in
 the steps put in good & efficient condition to
 continue as classed*

Committee Minute 28th March 1843

Character assigned 5 A 1

No. 1684 Survey held at London Date March 23rd 1843
 on the Bk Anna Master Moody
 Tonnage 460 Built at New Brunswick When built 1833
 By whom built _____ Owners J Graham
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 4860 Port of Dublin Lon 350 1841 Classed S S A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good & firm</u>	Timbers of the Frame <u>sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>new</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	<u>Copper</u>

General Observations and Opinion,
 as required by the Instructions,

*At the present time caulked from light water mark
 to the Waterway beam and appears in good & efficient
 condition to retain her present class*

Committee Minute 28th March 1843

Character assigned A 1