

# ANNUAL SURVEYS.

9669  
JH

No. 488 Survey held at London Date April 12 1843  
 on the My Sisters Master Falconer  
 Tonnage 260 Built at Hull When built 1818  
 By whom built — Owners Fraser & Co  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 515, 1646 Port of London Classed A.1  
13837, 3465, 4038, 4783, 5555, 6271, 8481,

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>Good &amp; sound</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>No</u>	Sails <u>Good</u>
Plank Shears <u>No</u>	Counter <u>No</u>	Cables <u>Good</u>
Waterways <u>No</u>	Plank and Treenails <u>No</u> (Outside to the Water's Edge.)	Anchors No. of <u>—</u>
Hatchway Comings <u>No</u>	Rudder <u>No</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>No</u>	Windlass <u>No</u>	Copper <u>—</u>

General Observations and Opinion,  
 as required by the Instructions,

Is in fair condition for the conveyance  
of dry and perishable cargo and may remain as  
classed

Committee Minute 18th April 1843

Character assigned —

Houtenay

No. 53 Survey held at London Date 12 April 1843  
 on the St. Catharine Master Kell  
 Tonnage 472 Built at New Brunswick When built 1841  
 By whom built — Owners Weller  
 Port belonging to London Destined Voyage Honduras  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 8676 Port of London Classed 5A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>No</u>	Pumps <u>Good &amp; Sufficient</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>No</u>	Masts, Yards, &c. <u>No</u> <u>No</u>
Spirkettling <u>Good</u>	Wales <u>No</u>	Sails <u>No</u> <u>No</u>
Plank Shears <u>No</u>	Counter <u>No</u>	Cables <u>No</u> <u>No</u>
Waterways <u>No</u>	Plank and Treenails <u>No</u> (Outside to the Water's Edge.)	Anchors No. of <u>No</u> <u>No</u>
Hatchway Comings <u>No</u>	Rudder <u>No</u>	Standing & Running Rigging <u>No</u> <u>No</u>
Breasthooks <u>No</u>	Windlass <u>No</u>	Copper <u>Good</u>

General Observations and Opinion,  
 as required by the Instructions,

The fastenings are firm, and she is in a  
good condition and may remain as classed

Committee Minute 18th April 1843

Character assigned 5

Houtenay



© 2019  
 Lloyd's Register  
 Foundation  
 LONG15-0109