

ANNUAL SURVEYS.

9706

No. 367 Survey held at London Date April 29 1843
on the B. Angerona Master Drysdale
Tonnage 171 Built at Leith When built 1839
By whom built _____ Owners Wright
Port belonging to Mercuriana Destined Voyage Seaborne
If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 616 Port of Leith Classed 6A1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|--|
| Decks | Transoms <u>Sound</u> | Capstan <u>Good</u> |
| Upper Deck Beams & Fastenings | Timbers of the Frame <u>Sound where seen</u> | Pumps |
| Lower Deck Beams & Fastenings | Topsides <u>Good</u> | Masts, Yards, &c. |
| Spirketting | Wales | Sails <u>Well found</u> |
| Plank Shears <u>Good</u> | Counter | Cables |
| Waterways | Plank and Treenails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging <u>Good</u> |
| Breasthooks | Windlass | Copper |

General Observations and Opinion, Presents a very firm appearance and is in a good
as required by the Instructions, sufficient state to retain her present Class

Committee Minute 5th May 1843

Character assigned 6A1

No. 329 Survey held at London Date April 1843
on the S. Champion Master J. Brame
Tonnage 132 Built at Southampton When built 1820
By whom built _____ Owners Bramwell
Port belonging to London Destined Voyage Genoa
If Surveyed Afloat or in Dry Dock St Katherine Dock

Original Survey, No. 1076 Port of London Continued 1839 Classed 4A1

The Surveyor is required to state the present Condition of the

| | | |
|--|---|----------------------------|
| Decks | Transoms <u>Sound</u> | Capstan |
| Upper Deck Beams & Fastenings <u>Good & firm</u> | Timbers of the Frame <u>Sound where seen</u> | Pumps |
| Lower Deck Beams & Fastenings | Topsides <u>Good</u> | Masts, Yards, &c. |
| Spirketting | Wales | Sails <u>Good</u> |
| Plank Shears | Counter | Cables <u>Good</u> |
| Waterways | Plank and Treenails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| Breasthooks | Windlass | Copper |

General Observations and Opinion, Is in a very sound & efficient state and may
as required by the Instructions, retain her present Class

Committee Minute 5th May 1843

Character assigned 4A1



© 2019

Lloyd's Register
Foundation

LONG15-0154