

REPORT of SURVEY for REPAIRS.

9719

No. 322 Survey held at Loda Date July 12th 1842
 on the Bk Boyne Master Wm Hammack
 Tonnage 620 Built at Calcutta When built 1816
 By whom built _____ Owners J. Jones
 Port belonging to Loda Destined Voyage Holifax
 If Surveyed Afloat or in Dry Dock Deftford

Original Survey, No. 4322, 7013, Dated 10/11 8068,
 Port Loda Classed FE, 1 Plastic

REPAIRS At the present time part and decks having six planks shifted
on the starboard side where the larboard did and the midship
part, in the main beam, & upper works caulked
new topmast rigging & backstay and the lower rigging overhauled

Present Condition of the	Transoms <u>Sound</u>	Windlass <u>Good</u>
Decks	Timbers of the Frame <u>Sound & new deck</u>	Capstan <u>"</u>
Upper Deck Beams & Fastenings	Topsides <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Counter <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Plank & Treennails <u>Good</u>	Cables <u>"</u>
Waterways <u>Firm</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings	Upper <u>Yellow Metal, good</u>	Standing & Running Rigging <u>Good & part new</u>
Breasthooks		
General Observations and Opinion	<p><u>This vessel is very strong & her fastenings no symptoms of weakness</u> <u>or decay and appears in every respect in good condition for the</u> <u>service & may continue FE, 1 with the British</u></p>	

The Amount of Fee.....£..... is received by me,

Committee's Minute 12th May 1843

Character assigned FE, 1 Anchor
LD