

# ANNUAL SURVEYS.

9/25

No. 147 Survey held at London Date May 4<sup>th</sup> 1843  
 on the 1<sup>st</sup> Dart Master Gray  
 Tonnage 97 0m Built at Southampton When built 1838  
 By whom built 74 4m Owners Gray  
 Port belonging to Portsmouth Destined Voyage   
 If Surveyed Afloat or in Dry Dock Smith & Westways

Original Survey, No. 57 Port of London Feb'y 1842 Classed 12 A 1  
Southampton, T's 108, Lon 6897, 8453:9713

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>Gm 1843</u>

General Observations and Opinion, Shipped - Caulked from the keel up and sheathed  
 as required by the Instructions, with Yellow Metal - She appears eligible to remain as  
Classed 12 A 1

Committee Minute 12<sup>th</sup> May 1843

Character assigned 12 A 1 Good

George Bayley

No. 295 Survey held at London Date May 4<sup>th</sup> 1843  
 on the 1<sup>st</sup> Dart Master Flight?  
 Tonnage 154 Built at Sunderland When built 1839  
 By whom built 158 Owners Foster Smith  
 Port belonging to London Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock Smith & Westways

Original Survey, No. 11457 Port of London April 1842 Classed 10 A 1  
Sunderland, Lon 7883, 8621, 9150.

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>up 1843</u>

General Observations and Opinion, Wales & Topsides Caulked - Keel recoppered - Copper  
 as required by the Instructions, repaired - She is in an efficient state and in my  
opinion eligible to remain as Classed 10 A 1

Committee Minute 12<sup>th</sup> May 1843

Character assigned 10 A 1 Good

George Bayley



May 8

6 Annual

1 Repair

3<sup>rd</sup> Damage

---

10

---



© 2019

Lloyd's Register  
Foundation