

# ANNUAL SURVEYS.

9760

No. 275 Survey held at London Date 15 May 1843  
 on the Ship "Northumberland" Master Warner  
 Tonnage 684 Built at Rangoon When built 1838  
 By whom built                      Owners R Green  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Mr Green's Dock

Original Survey, No. 5418, 8659 Port of London

Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Doitto</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Doitto</u>
Waterways <u>Good</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>Doitto</u>
Hatchway Comings <u>Good</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Doitto</u>
Breasthooks <u>Good</u>	Rudder <u>Good</u>	Copper <u>Good Patched</u>
	Windlass <u>Good</u>	

General Observations and Opinion,  
as required by the Instructions,

at this time the Copper Patched and  
dressed & upper works Caulked and  
as she is in efficient Condition May

Committee Minute 23<sup>rd</sup> May 1843

Character assigned 12 A1

*Joseph H. Hatcher*

*Joseph H. Hatcher*

No. 185 Survey held at London Date 17 May 1843  
 on the Ship "Owen Glendower" Master Hopkins  
 Tonnage 911 Built at London When built 1829  
 By whom built Green Wigram & Green Owners R Green  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Mr Green's Dock

Original Survey, No. 5458, 6279 Port of London

Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Doitto</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Doitto</u>
Waterways <u>Good</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>Doitto</u>
Hatchway Comings <u>Good</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Doitto</u>
Breasthooks <u>Good</u>	Rudder <u>Good</u>	Copper <u>New Yellow Metal</u>
	Windlass <u>Good</u>	

General Observations and Opinion,  
as required by the Instructions,

at this time the bottom was stripped and  
Caulked & resheathed with Yellow Metal  
Her upper works were also Caulked and  
as she is in efficient Condition May

Committee Minute 23<sup>rd</sup> May 1843

Character assigned 12 A1

*Joseph H. Hatcher*

*Joseph H. Hatcher*